Name(s) of Risk Team Members: P. Ribaudo, W. McKeon, G. Herbst, J. Durnan			Point Val Paramet		1				2 3		4			5				
Tob Title: Cryo Operations during Experimental Magnet Test				ncy	≤once/year				:	≤once/month	≤once/week	≤once/shift			>once/shift			
Job Description:	b Number or Job Identifier: 28-06 b Description: anaging Cryo for Experimental testing of magnets - Vertical Test Facility			ty	First Aid Only			nly	Me	edical Treatment	eatment Lost Time		Partial Disability			Death or Permanent Disability		
Training Procedures List (Optional): Applicable Standard Operating Procedures: 8.1.3 Series  Approved by: £. Lessard Date: 6-2-06 Rev. #: 0			Likeliho (D)	Extremely Unlikely				Unlikely		Possible	Probable			Multiple				
Stressors (if applicable Noise, Low Light leve	e, please list all):		on for Revision	n (if app	olicab	le):					Comments:							
								nal Cor	itrols				Af	ter Ac	lditior	nal Coi	ntrols	
Job Step / Task	Hazard	Control(s)		Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	Control(s) A	dded to Reduce Risk	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	% Risk Reduction
Hook up of new sample	Working with hand tools	Training, PPE		Y	2	4	1	2	16									
Hook up of new sample	Tripping	Training, Safety Shoes, housekee	ping	Y	2	4	1	2	16									
Leak Check system	Pressurized system (10 psi)	training, PPE		Y	1	4	1	1	4									
Pump and Purge	Noise	Training, procedures, PPE, Minir source	nize time at	Y	2	4	4	1	32									
Cool down of system	Quench - cold temperature	Training, leak check		Y	2	4	4	1	32									
Electrical Testing Quench	Quench - cold temperature	Training, leak check, quench valv		Y	2	4	4	1	32									
Warm-up completion of test	Quench - cold temperature	Training, leak check, quench valv	/es	Y	2	4	4	1	32									
Warm-up completion of test	Hand tools	Training, PPE		Y	2	4	1	2	16									
Hook up of new sample	Working with hand tools	Training, PPE		Y	2	4	1	2	16									
Hook up of new sample	Tripping	Training, Safety Shoes, housekee	ping	Y	2	4	1	2	16									

Leak Check system	Pressurized system (10 psi)	training, PPE	Y	1	4	1	1	4					
Pump and Purge	Noise	Training, procedures, PPE, Minimize time at source	Y	2	4	4	1	32					
Further Description of Controls Added to Reduce Risk:													
*Risk:	0 to 20	21 to 40			41-60	-60			61 to 80		81 or greater		
	Negligible	Acceptable	Moderate						Substantial		Intolerable		